

Increase your comfort

We offer numerous accessories so you can configure your 3M™ Speedglas™ Welding Helmet G5-01 to meet your individual preferences and application needs.



16 92 00



16 90 22



16 90 43



16 90 20



16 90 41



16 90 42

16 90 35



16 90 30



16 91 00

83 72 42
83 75 42

83 71 10



83 71 20



BPK-01



83 50 20



83 40 18



16 90 21



16 90 23

Part No	Description
16 90 20	Head protection in fabric
16 90 21	Head protection in fluorescent yellow
16 90 22	Head protection in leather
16 90 23	Head protection in fabric (large)
16 90 24	Scrape guard (not shown)
16 90 30	Shroud
16 90 35	Extended cover kit (shroud and large head cover in fabric)
16 90 41	Neck protection in fabric (small)
16 90 42	Neck protection in fabric (large)
16 90 43	Neck protection in leather
16 92 00	Task light, incl mounting parts and cables
16 92 05	Protection plate for task light, pkg. of 5
16 92 10	Long power cable for task light
16 92 11	Short power cable for task light
16 92 23	Pouch with Adflo battery, for task light when using supplied air regulator (not shown)

Part No	Description
83 40 18	Flame resistant breathing tube cover (recommended when using the task light).
83 50 20	Braces for respirator
83 71 10	Adflo odour filter
83 71 20	Odour filter pad
83 72 42	Adflo gas filter A1B1E1
83 75 42	Adflo gas filter A2
BPK-01	Back pack for respirator

3M™ Versaflo™ Supplied Air Regulators



V-100E



V-200E




V-500E

V-100E	Air cooling regulator
V-200E	Air heating regulator
V-500E	Flow controlled regulator

For further details to buy a complete supplied air system please reference the 3M Welding Safety Catalogue.

Spare parts and consumables



Part No	Description	Part No	Description	Part No	Description
11 00 10	Passive welding filter lens shade 10 (90×110)	52 70 01	Outer protection plate (scratch +), pkg of 10	61 30 00	Visor plate, anti-fog and hardcoated, pkg. of 5
11 00 11	Passive welding filter lens shade 11 (90×110)	52 70 70	Outer protection plate (heat), pkg of 10	61 32 00	Headband with assembly parts
11 00 12	Passive welding filter lens shade 12 (90×110)	52 80 25	Inner cover plate, pkg of 5	61 37 00	Air duct breathing tube (short) incl. holder
11 00 13	Passive welding filter lens shade 13 (90×110)	53 62 10	Cushion part for headband G5-01	61 37 01	Holder for breathing tube
12 60 00	Inner cover plate for passive filter	53 62 11	Large head rest	61 40 00	Face seal
16 90 20	Head protection in fabric (small)	60 10 00	Battery holder	61 60 00	Pivot and sliding mechanism, including pivot knobs
16 90 40	Neck protection rigid	60 20 00	Battery CR2450	61 60 01	Pivot rings for outer shield
17 10 20	Magnifying lens 1.0X	61 00 11	Speedglas passive welding filter kit G5-01 (shade 11)	61 60 02	Pivot knobs
17 10 21	Magnifying lens 1.5X	61 00 20	Speedglas welding filter G5-01TW	61 60 03	Headband back part
17 10 22	Magnifying lens 2.0X	61 00 30	Speedglas welding filter G5-01VC	61 78 00	Helmet G5-01, without welding filter, with 3M™ Adflo™ Powered Air Repirator
17 10 23	Magnifying lens 2.5X	61 01 95	Outer shield	61 78 09	Helmet G5-01, without welding filter, with 3M™ Adflo™ Powered Air Repirator and consumable starter kit
17 10 24	Magnifying lens 3.0X	61 05 00	Front cover for inner visor	79 01 05	Carry Bag
17 10 35	Magnifying lens holder	61 05 01	Front cover for flip-up	79 20 00	Consumable starter kit G5-01, includes 3 different sweatbands, face seal, visor plate, inner and outer cover plates.
19 71 55	Hinge mechanism, 1 pair	61 11 00	Welding helmet G5-01, without welding filter		
19 80 16	Sweatband (towelling), pkg of 3	61 11 90	Welding helmet G5-01, without welding filter, without neck or head protection		
19 80 17	Sweatband (fleecy cotton), pkg of 3	61 11 95	Inner shield with airtight seal and airflow controls (including visor frame)		
19 80 18	Sweatband (leather)				
52 60 00	Outer protection plate (standard), pkg of 10				
52 70 00	Outer protection plate (scratch), pkg of 10				